TOSHIBA

FILE NO. 810-200553GR

SERVICE MANUAL

DVD VIDEO PLAYER

SD-350ESB2
SD-350ESE2



The above model is classified as a green products (*1), as indicated by the underlined serial numbers. This Service Manual describes replacement parts for green products. When repairing any green products, use the parts described in this manual and lead-free solder (*2).

For (*1) and (*2), see the next page.

© TOSHIBA CORPORATION 2006

Jan., 2006 (AL)GREEN

(*1) GREEN PRODUCT PROCUREMENT

The EC is actively promoting the WEEE & RoHS Directives that define standards for recycling and reuse of Waste Electrical and Electronic Equipment and for the Restriction of the use of certain Hazardous Substances. From July 1, 2006 , the RoHS Directive will prohibit any marketing of new products containing lead.

Increasing attention is given to issues related to the global environmental. Toshiba Corporation recognizes environmental protection as a key management tasks, and is doing its utmost to enhance and improve the quality and scope of its environmental activities. In line with this, Toshiba proactively promotes Green Procurement, and seeks to purchase and use products, parts and materials that have low environmental impacts.

Green procurement of parts is not only confined to manufacture. The same green parts used in manufacture must also be used as replacement parts.

(*2) LEAD-FREE SOLDER

This product is manufactured using lead-free solder as a part of a movement within the CE industry at large to be environmentally responsible. Lead-free solder must be used in the servicing and repair of this product.
The melting temperature of lead-free solder is higher than that of leaded solder by 86°F to 104°F (30°C to 40°C). Use of a soldering iron designed for lead-based solders to repair product made with lead-free solder may result in damage to the component and or PCB being soldered. Great care should be made to ensure high-quality soldering when servicing this product — especially when soldering large components, through-hole pins, and on PCBs — as the level of heat required to melt lead-free solder is high.

WARNING

This product is manufactured using lead free solder.

DO NOT USE LEAD BASED SOLDER TO REPAIR THIS PRODUCT !

PARTS LIST

Location No.	TSB P/N	Reference No.	Description	
	AH700317	043-000168W010	REMOTE CONTROL HANDSET SE-R0168 (C.G), w/WEEE MARK	
	AH700052	122-004220W151	AV CABLE1.5M COAXIAL	
⚠	AH700277	134-A14332W016	PCA-VDE-6'5&-VDENNM	(For TE, TB Version)
⚠	AH700318	134-A14342W002	PCA-BSI-6.5"&-VDENNM	(For TF Version)
⚠	AH700319	811-350E91W011	MANUAL - (ENG)	(For TE, TB Version)
⚠	AH700320	811-350E91W021	MANUAL - (FRE)	(For TF Version)
⚠	AH700321	811-350E91W032	MANUAL - (GER)	(For TE Version)
⚠	AH700322	811-350E91W040	MANUAL - (ENG)	(For TF Version)
⚠	AH700323	811-350E91W052	MANUAL - (SWE)	(For TE Version)
⚠	AH700324	811-350E91W062	MANUAL - (FIN)	(For TE Version)
⚠	AH700325	811-350E91W072	MANUAL- (DAN)	(For TE Version)
⚠	AH700326	811-350E91W081	MANUAL - (NOR)	(For TE Version)
⚠	AH700327	811-350E91W091	MANUAL - (POL)	(For TE Version)
⚠	AH700328	811-350E91W102	MANUAL - (CZECH)	(For TE Version)
⚠	AH700329	811-350E91W111	MANUAL - (HUNG)	(For TE Version)
⚠	AH700330	811-350E91W120	MANUAL - (GREEK)	(For TE Version)
⚠	AH700331	811-350E91W131	MANUAL - (BULG)	(For TE Version)
⚠	AH700332	811-350E91W141	MANUAL - (SPAN)	(For TE Version)

SAFETY PRECAUTION

The parts identified by ⚠ mark are critical for safety. Replace only with part number specified. The mounting position of replacement is to be identical with originals. The substiute replacement parts which do not have the same safety characteristics as specified in the parts list may create shock, fire or other hazards.

TOSHIBA CORPORATION
1-1, SHIBAURA 1-CHOME, MINATO- KU, TOKYO 105-8001, JAPAN